SOUND ANALYTICAL SERVICES, INC.

SPECIALIZING IN INDUSTRIAL & TOXIC WASTE ANALYSIS

4813 PACIFIC HIGHWAY EAST, TACOMA, WASHINGTON 98424 · TELEPHONE (206)922-2310 · FAX (206)922-5047

Report To: Ash Grove Cement   Date: May 16, 1991

Report On: PCB in Oil   Lab No.: 17654

IDENTIFICATION:
Samples Received on 05-16-91
P.O. No. S1135
Neutral Driving Transformer

ANALYSIS:

Laboratory Sample No.	Client Identification	PCB Type	PCB (mg/kg)
RUSH 1	S/N H-216538-68P	1260	890

SOUND ANALYTICAL SERVICES

BRENT HEPNER

AGC2F000099

SOUND ANALYTICAL SERVICES, INC.

SPECIALIZING IN INDUSTRIAL & TOXIC WASTE ANALYSIS

4813 PACIFIC HIGHWAY EAST, TACOMA, WASHINGTON 98424 · TELEPHONE (206)922-2310 · FAX (206)922-5047

QUALITY CONTROL REPORT

Average (1) Method Blank = < 0.01 mg/l

EMSL QUALITY CONTROL REPORT

Sample Matrix - Transformer Oil
Units: mg/kg

Compound	Weight	Dilution	True Value (TV)	Result	*RPD
1254	0.1000		50.0	46.0	8.3

* RPD = [(TV-R)/(TV+R)/2)] X 100

SOUND ANALYTICAL SERVICES, INC.

SPECIALIZING IN INDUSTRIAL & TOXIC WASTE ANALYSIS

4813 PACIFIC HIGHWAY EAST, TACOMA, WASHINGTON 98424 · TELEPHONE (206)922-2310 · FAX (206)922-5047

Report To: Ash Grove Cement   Date: May 16, 1991

Report On: PCB in Oil   Lab No.: 17654

IDENTIFICATION:
Samples Received on 05-16-91
P.O. No. S1135
Neutral Driving Transformer

ANALYSIS:

Laboratory Sample No.	Client Identification	PCB Type	PCB (mg/kg)
RUSH 1	S/N H-216538-68P	1260	890

SOUND ANALYTICAL SERVICES

Brent Hepner
BRENT HEPNER

SOUND ANALYTICAL SERVICES, INC.

QUALITY CONTROL REPORT

Average (1) Method Blank = < 0.01 mg/l

EMSL QUALITY CONTROL REPORT

Sample Matrix - Transformer Oil
Units: mg/kg

Compound	Weight	Dilution	True Value (TV)	Result	*RPD
1254	0.1000		50.0	46.0	8.3

* RPD = [(TV-R)/(TV+R)/2)] X 100